

Figure 2




Figure 3(a)






Figure 3(b)



11

Figure 3(c)



5/11




Figure 4: Heat Recovery Efficiency as a Function of Wash Dilution Factor

6/11




Figure 5: Blow Line Heat Loss as Function of Operating Conditions and Wash Zone DF.

7/11




Figure 6: Total Medium Pressure Steam Demand as Function of Operating Conditions and Wash Zone DF.

8/11




Figure 7: Blow Line Temperature Gradients Before and After Filtrate-Header Modification. The gradient was not eliminated.

9/11

Modified Cook Header Temperature




Figure 3: Modified Cook Header Temperature Gradients Before and After Header Modification.

10/11




Figure 9: Extraction Header Temperature Gradients Before and After Header Modification.

11/11




Figure 10: Effect of Filtrate-Header Modification on Cooking Uniformity